

- in case registrar redundancy is activated, license restriction is applied since pbx receives double registrations
- wp 500/600 don't recognise borders between sip messages present in the same package when using tls
- phones do not support codecs different from the first one in sdp
- xml browser returns to the main page of phone menu instead of the last selected page after dial action
- after changing "local sip port" phones continue receiving sip messages to port 5060/udp
- phones are reconnected with a big delay after audio re-invite
- cid name is not present on phone display after answer to call completion request
- phones do not support calls to feature code with three asterisk symbols
- phones don't have parameter for setting a random listening sip port
- types of call forwards activated for the account are not displayed on phone's display
- blf keys of the previous user are displayed after logout
- incorrect visualization of long caller names (over 25 chars) on phone display
- behavior of line keys configured as blf: solid green = idle; blinking = busy; rapid blinking = incoming call
- voicemail led is off for 30 minutes after reboot of wp600
- missing ring of the second incoming call after hangup of the first one
- dtmf inband do not work for outgoing calls during early media unless default dtmf setting is changed on wp side
- under certain conditions, search in some phonebook could return no results; to resolve this issue, leave the phonebook search menu and try again
- in case of setting a custom ringtone on wp400 (not RingX), it's impossible to adjust the ringer volume